

Technical Bulletin

Patio Lock Jamb Reinforcing

SPECIFIC PRODUCT	DOCUMENT CATEGORY	DATE		REV.	REFERENCE	PAGE
PATIO DOORS	PRODUCT SUBSTITUTION	SEP	2020	0	PMT2004	01

Due to unforeseen circumstances we would like to inform you that there will be a break in supply on Patio Lock Jamb Steel: Part Numbers **1258 & 125817**. This is with immediate effect and will continue for up to one month. During this period we will be substituting 1258 with a slightly shorter 1.8m length. Unfortunately 125817 will not be available during this time. Please be assured that every effort is being taken to make these parts available as soon as possible.

MANUFACTURE

The new section is 28mm shorter than the part it replaces, but can be used as a direct replacement. If a shorter length is required this can be cut down. As a guide the substitute section is suitable for sashes 1970mm and up.

PRICE

No change.

ORDERING

Please continue to order part number 1258 as we will substitute the stock at source. Any existing orders for 125817 will be moved over onto 1258.

Should you require any further information or clarification, please contact your Customer Services Advisor or the Technical Department.